

Result of the R-20000 Pinta Rulli treatment after a few months of work..

In the images we can clearly see the great difference of the rollers treated with our **R-20000** Pinta Rulli treatment that appear in the photographs marked with the arrow and painted at the end with orange.

On rollers treated with R-20000 it can be seen that:

- No dirt has adhered
- The chemical attack has not penetrated







